

SUNWAVE Platform Upgrade Operation Instructions

- 1. Upload firmware: The upgraded firmware has been uploaded to the SUNWVAE monitoring platform, the name is: H910-07000-26**

ID	Firmware Type	Name	Firmware Version	Model	Uploader	Upload Time	Remarks
4839	Inverter	H910-07000-26.bin	26	HMS-0.6K/0.8K	zhaowei.hu@slenergy.com	2024-09-20 13:36:43	H910-07000-26

- 2. Find the inverter that needs to be upgraded**

Find out inverter SN number: In the device menu, search for the inverter SN number that needs to be upgraded in the inverter search bar.

Status	Inverter SN	Device Name	Inverter Model	Firmware Version	Dongles SN	Today Generation [kWh]	Total Generation	Operation
Online	P0834KA023701697	-----	SL-M800-C	V1.0.0.24	P0834KA023701697	0.01	434.84	---
Online	P0834KA023702606	-----	SL-M800-C	V1.0.0.24	P0834KA023702606	0.01	421.14	---
Online	P0834KA023701655	-----	SL-M800-C	V1.0.0.24	P0834KA023701655	0.21	445.36	---
Online	P0834KA023702425	-----	SL-M800-C	V1.0.0.24	P0834KA023702425	0.01	506.15	---
Online	P0834KA023701042	-----	SL-M800-C	V1.0.0.24	P0834KA023701042	0.03	583.14	---
Online	P0834KA023701514	-----	SL-M800-C	V1.0.0.24	P0834KA023701514	0.03	462.71	---
Online	P0834KA023701024	-----	SL-M800-C	V1.0.0.24	P0834KA023701024	0.05	484.59	---
Online	P0834KA023700978	-----	SL-M800-C	V1.0.0.24	P0834KA023700978	0.07	541.86	---
Online	P0834KA023703448	-----	SL-M800-C	V1.0.0.24	P0834KA023703448	0.01	398.6	---
Online	P0834KA023700034	-----	SL-M800-C	V1.0.0.24	P0834KA023700034	0.63	341.1	---



Status	Inverter SN	Device Name	Inverter Model	Firmware Version	Dongles SN	Today Generation [kWh]	Total Generation	Operation
Online	P0834KA023600019	-----	SL-M800-C	V1.0.0.24	P0834KA023600019	0	20.14	---



Status	Inverter SN	Device Name	Inverter Model	Firmware Version	Dongles SN	Today Generation [kWh]	Total Generation	Operation
Online	P0834KA023600019	----	SL-M800-C	V1.0.0.24	P0834KA023600019	0	20.14	...

NOTICE: The current power generation must be greater than 100W for updating device.

Firmware category: Inverter

* Remarks: Please select firmware remark

Buttons: Cancel, OK

Firmware category: Inverter

* Remarks: Please select firmware remark

Selected option: H910-07000-26 (2024-09-20 13:36:43)

Buttons: Cancel, OK

Basic Information (System ID 1513088521814384640)

Inverter SN	P0834KA023600019	Model	SL-M800-C	Version	V1.0.0.24
System Name	Kraftwerk Micha	Dongles SN	P0834KA023600019	Event	

Progress: 50%

Start upgrade: Command received successfully | File download succeeded | Upgrading | Upgrade successfully

Statistics:

Current Power	Today Generation	Generation For The Month	Total Generation	F/A Of Last Hour
26 [W]	0.01 [kWh]	20.15 [kWh]	20.15 [kWh]	0

NOTICE:

1. The total time to complete the upgrade of an inverter is requested about eight minutes. (Which the software upgrade process is about spend five minutes).
2. During the upgrade process, keep the DC power supply normal (voltage between 25 and 55 volts) and network communication good. The current power generation power of the inverter must be greater than 100W. If the upgrade fails, please try again the instruction steps.